

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024616**Date Inspected:** 17-Jan-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Changxing Island **Location:** Shanghai, China**CWI Name:** Ji Cai Fang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Vikram Singh was present during the times noted above for observations relative to the work being performed at ZPMC.

NDT

OBG Bay 14

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No 08208.

Magnetic Particle Testing (MT)

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG. The weld designations reviewed is as follows:

SEG3013AX-135, 139, 206, 207

WELDING

OBG Bay 14

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector randomly observed the following work in progress:

Shielded Metal Arc Welding (SMAW)

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as Seg3015J-011 located on Floor Beam of the OBG Segment 13CW. The welder is identified as 067993. ZPMC Quality Control (QC) is identified as Mr. Wang Xiang Pin. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-Tc-U4b-FCM-1.

This QA Inspector observed the welding operation per the SMAW process on a weld joint identified as Seg3015L-011 located on Floor Beam of the OBG Segment 13CW. The welder is identified as 037932. ZPMC Quality Control (QC) is identified as Mr. Wang Xiang Pin. The welding variables recorded by QC appeared to comply with WPS-B-P-2212-Tc-U4b-FCM-1.

Flux Cored Arc Welding (FCAW)

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3015-001 located on Deck Panel of the OBG Segment 13CW. The welder is identified as 066734. ZPMC Quality Control (QC) is identified as Mr. Wang Xiang Pin. The welding variables recorded by QC appeared to comply with WPS-B-T-2231-ESAB.

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3015H-003 located on the OBG Segment 13CW. The welder is identified as 045227. ZPMC Quality Control (QC) is identified as Mr. Wang Xiang Pin. The welding variables recorded by QC appeared to comply with WPS-B-T-2232-ESAB.

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3014F-125 located on the OBG Segment 13BW. The welder is identified as 045143. ZPMC Quality Control (QC) is identified as Mr. Wang Xiang Pin. The welding variables recorded by QC appeared to comply with WPS-345-FCAW-3G (3F)-ESAB-Repair and B-WR19634.

This QA Inspector observed the welding operation per the FCAW process on a weld joint identified as Seg3020L-095 located on Floor Beam at the PP127 of the OBG Segment 14W. The welder is identified as 201215. ZPMC Quality Control (QC) is identified as Mr. Liu Fang. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-ESAB.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Singh,Vikram	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer
